

To: Rendon, Laura, NMENV[Laura.Rendon@state.nm.us]
From: Garcia, David
Sent: Thur 8/13/2015 7:34:17 PM
Subject: FW: Gold King Mine - Procedure to remove of advisories

please print, thank you.

David F. Garcia

Deputy Director

Water Quality

Protection Division

U.S. EPA Region 6

1445 Ross Avenue (Mail Code: 6WQ-D)

Dallas, Texas 75202-2733

Phone: (214) 665-7593

Follow EPA Region 6



From: Rauscher, Jon
Sent: Thursday, August 13, 2015 2:31 PM
To: Trais NMENV Kliphuis (trais.kliphus@state.nm.us)
Cc: Garcia, David; Webster, Susan; Petersen, Chris; Foster, Althea; Smith, Monica; Loesel, Matthew; Restivo, Angela; Crossland, Ronnie; Edlund, Carl; Ngo, Kim; Fanning, Cynthia
Subject: Gold King Mine - Procedure to remove of advisories

What is the proposal / procedure that New Mexico will use for removing an advisory?

What is the data and scientific basis needed to support your decision?

What is your anticipated order or sequence to remove an advisories?

- Groundwater
- Surface water
- Ditches

The validated data that Region 6 currently has in our possess:

- Surface water for Friday, Aug 7 and Saturday, Aug 8

Region 6 should receive the following validated data today (August 13) that we shared with you yesterday (August 12):

- Surface water for Sunday, Aug 9 (9 locations) and Monday, Aug 10 (9 locations)
- Sediment for Monday, Aug 10 (1 location)
- Groundwater for Monday, Aug 10 (10 locations)

Region 6 should receive the following preliminary data today (August 13):

- Surface water for 9 locations
- Sediment for 9 locations
- Groundwater for 30 locations

